

# Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



### **WORK ORDER INFORMATION**

Work Order Name: WO/80008KN0767/1

Work Order Type: Weatherization

Audit Name: 80008KN0767-Audit

#### **CLIENT INFORMATION**

Client Name:

Address:

Client ID: 80008KN0767

Alt. Client ID: KNOX

## AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number.	
Contractor's Signature:	

#### **COMMENT**

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Home built in 1970

An EPA Certified Firm/Renovator is required.

## Measures

1	<i>Measure</i> 1 Duct	Insulation (Return)(2')			Componen	ts			Inspected
С	No chan	n must be a minimum of ges allowed. Refer to Ap s and Southeast Field Gu	pendix A-	Stand	lards for Wea	atherizat	iate tap	e. Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Duct Insulation	Linear Foot	2					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Linear Foot	2		·///			
0	ther Detail								
			-			TURNET.			
				Measur	e Sub Total:		]	Sub Total:	
	Field Notes:	August Valentin					-		

Page 2 of 11

ı	Measure 2 Mast	tic the Return Box(QTY	2)		Component	ts			Inspected
C	Use foar return bo allowed.	hite Mastic to be applied m board around edges to ox where it meets return r Refer to Appendix A- Sta st Field Guide.	fill in any egister w	∕ voids ⁄ith app	and mastic. ropriate caul	Seal fro lk. No c	nt of hanges		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Mastic the Return Box	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
O	ther Detail								
				Measur	Sub Total:		] ;	Sub Total:	
Γ	Field Notes:			****			<u> </u>		

Client ID: 80008KN0767 Alt. Client ID: KNOX

Work Order Name: WO/80008KN0767/1 Report Run On: 5/8/2010

Page 3 of 11

4	weasure	3 Mas	tic/Insulate Supply Bo	ot(QTY 9)		Componen	ts			Inspected
С	omment	of boot was be insula cell foan	hite Mastic to be appliewhere it meets subfloor ated on outside of boot n. No changes allowed. rization Materials and S	to be caulk to R-6. This Refer to A	ed wit s is be ppendi	h appropriate st performed x A- Standai	e caulk. I with 2-p	Boots to	, )	
		NOTE:W none ove pascals.	Vhen post audit is perfo er 3 pascals and not mo	rmed, all bo ore than 3 b	oots m	ust be below ver 1 pascal	1 pasca but less	l with than 3		
						Estimated			Actual	
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construc	tion Mate	Mastic/Insulate Supply Boot	Each	9					10/
2	Labor		Labor	Each	9					
0	ther Detail	<u>.</u>								
	.=									
				ı	Measur	e Sub Total:	******	]	Sub Total:	:
	Field Note	s:	1700	***************************************		V 90.4114	*****			
										ŀ

Order Name: WO/80008KN0767/1 Report Run On: 5/8/2010

Page 4 of 11

Measure 4 DV	VH Pipe Insulation			Componen	ts			Inspected	
Comment									
			Estimated				Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DHW Pipe Insulation	Each	1						
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.			L			J (	•	
2 Labor	DHW Pipe Insulation	Each	1		1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				
Other Detail									
			Measui	e Sub Total:			Sub Total:		
Field Notes:				<del>,</del>					
ĺ								Achie	

	Measure	5 F	Floor	Ins. R-19				Componen	ts F1			Inspected
C	Comment	Star subf (e.g. com	ore ins ndard floor a . stav press	labor cost. Contrestalling insulation.  s. Insulation is in above (paper side es for blankets). sions. Refer to Appeast Field Guide	Contra stalled agains Insulat opendix	ictor to in to mainta it subfloo ion to hav	istall u ain per or) inclu ve NO	sing Resnet manent cont iding necess gaps, voids,	Grade 1 act with sary support	the ports	8	
<b>1</b> 1	44-41-1			B 14 40				Estimated			Actual	
Ħ	Material /	Lapo	r	Description / Comm	1en <b>t</b>	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	n		Floor Insulation - Fiberglass Batts - F	₹-19	SqFt	50					
2	Labor			Floor Insulation  - Fiberglass Batts - F	₹-19	SqFt	50		***************************************			
<u>c</u>	Other Detai	ı		, ukim a						7		
						ı	Measur	e Sub Total:	****		Sub Total:	
	Field Note	es:							T V TT A G GF ALAMMA			

٨	<i>leasure</i> 6 DWH	l Tank Insulation			Components					
Co	omment extend p	ressure relief pipe as ne	eded							
				Estimated				Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Hot Water Equipm	DHW Tank Insulation	Each	1					<u></u>	
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	DHW Tank Insulation	Each	1						
Ot	her Detail									
						7.7				
				Measur	e Sub Total:			Sub Total:		
F	ield Notes:	110		<del></del>						
L									1	

Measure 7 Due	ct Insulation			Componen	ts			Inspected
tape. N	tion must be a minimum o lo changes allowed. Refer als and Southeast Field Go	to Apper	ndix A- S	Standards fo	n <i>Actual</i>			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Duct Insulation	SqFt	13.33			][ ]		10.07
	Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.					J []		
2 Labor	Duct Insulation	SqFt	13.33		770			
Other Detail								,
					<u>-</u>			
		· · · · · · · · · · · · · · · · · · ·	Measure	Sub Total:		] s	ub Total:	
Field Notes:								

	Measure	8	Attic	Ins. R-19			Componer	its A1			Inspected
•	Comment •Includes labor cost. Contractor to install 1 ruler for every 300 square foot of attic space showing depth of insulation. Build insulation dam around attic access. Install baffles as needed to prevent loose fill insulation from entering soffit and covering vent. Seal all holes, gaps, and penetrations in attic before insulating. Seal around chimney with sheet metal and high temperature silicone or fire resistant foam. Install R-30 fiberglass batt secured to attic access and weather strip with foam tape. Contractor to install using Resnet Grade 1 Standards. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.										
							Estimated	1		Actual	
#	Material /	Labo	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulatio	n		Attic Insulation - Blown Fiberglass - R-19	SqFt	816					
2	Labor			Attic Insulation - Blown Fiberglass - R-19	SqFt	816					
_	Other Detai	1		- FILL							
	***										
								***			
					ı	Measur	e Sub Total:		]	Sub Total:	
	Field Note	s:				700					

Client ID: 80008KN0767 Alt. Client ID: KNOX Work Order Name: WO/80008KN0767/1 Report Run On: 5/8/2010

Version 8.6.0 Page 9 of 11

		mproper Venting of Bat aust Fan	throom		Component	ts			nspected
C	<b>Comment</b> Bath Ver Attachm Guide.	nts installed to outside of ent A- Standards for We	home. No atherizatio	o chan on Mat	ges allowed. erials and Sc	Refer to outheast	Field		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Bath Vent w/ Piping to Outside	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
<u>_</u>	Other Detail								
L		- Contract							
						- v.			
			ı	Measur	e Sub Total:			Sub Total:	
	Field Notes:		*******	•	PRIVAL.	TOTAL STATE OF THE			
ŀ									

Report Run On: 5/8/2010

Measure 10 Fix	Ventilation Inadequate	(Attic) 4 C	YTÇ	Componen	ts			Inspected
Ventala 1/2 low.	ents installed on High & I ting Area of 1/150 of the No changes allowed. Re prization Materials and Se	e area of species	pace b ichmer	eing ventilatent A- Standa	ed.1/2 h	igh and		
NOTE: 2 high 2	Do not install roof vents Plow	on front pa	rt of h	ouse.  Estimated			Andread	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
1 Health and Safety	•	Each	4		IOtal	wiy		rotar
2 Labor	Labor	Each	4		· · · · · · · · · · · · · · · · · · ·			
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Fleld Notes:						.,,,,,,,		
		Work Or	der Gra	nd Total:		Gran	d Total:	

DOE Weatherization Assistant Version 8.6.0 Page 11 of 11

Report Run On: 5/8/2010